


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-100	Smoke	10/14/2008	ADS/TM	S09MM_013MH	Dry	Yes	1,751.06



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-100	Smoke	10/14/2008	ADS/TM	S09MM_013MH	Dry	Yes	1,751.06

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11MM_006G1	S11MM_006MH	S11MM_031MH	73.71223	10
S09MM_013G1	S09MM_013MH	S09MM_011MH	266.9394	8
S11MM_031G1	S11MM_031MH	S11MM_038MH	176.192	10
S11MM_030G1	S11MM_030MH	S11MM_006MH	153.1447	8
S09MM_004G1	S09MM_004MH	S09MM_013MH	287.1956	8
S09MM_011G1	S09MM_011MH	S11MM_023MH	276.2451	8
S11MM_038G1	S11MM_038MH	S11MM_029MH	245.4158	10
S11MM_023G1	S11MM_023MH	S11MM_018MH	203.5713	8
S11MM_018G1	S11MM_018MH	S11MM_030MH	42.197	8
S11MM_058G1	S11MM_058DE	S11MM_030MH	26.45039	8

Observations & Photos

Obs_ID S1028-100-OB01

Address 3308 Elgin Ave


Status Private

Source Cleanout

Location Yard - side

Nearest MH S09MM_013MH

Comments Smoke from cleanout in front yard. 3308 Elgin Ave.



Picture \S1028-100-OB01-P01.jpg

Comments Front of house, 3308 Elgin Ave.

Obs_ID S1028-100-OB02

Address 3306 Elgin Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09MM_013MH

Comments Smoke from cleanout in front yard. 3306 Elgin Ave.



Picture \S1028-100-OB02-P01.jpg

Comments Front of house, 3306 Elgin Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-100	Smoke	10/14/2008	ADS/TM	S09MM_013MH	Dry	Yes	1,751.06

Obs_ID S1028-100-OB03

Address 3309 Elgin Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09MM_004MH

Comments Smoke from cleanout in front yard. 3309 Elgin Ave.



Picture \S1028-100-OB03-P01.jpg

Comments Front of house, 3309 Elgin Ave.

Obs_ID S1028-100-OB04

Address 3301 Elgin Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S09MM_013MH

Comments Smoke from cleanout in front yard. 3301 Elgin Ave.



Picture \S1028-100-OB04-P01.jpg

Comments Side of house, 3301 Elgin Ave.

Obs_ID S1028-100-OB05

Address 3131 Gwynns Falls Pkwy


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11MM_031MH

Comments Smoke from cleanout in front yard. 3131 Gwynns Falls Pkwy



Picture \S1028-100-OB05-P01.jpg

Comments Front of house, 3131 Gwynns Falls Pkwy